



## N.H. DES SUBSURFACE SYSTEMS BUREAU REPAIR / REPLACEMENT REPORT - Env-Wo 1003.10(c)

## FILE PRIOR TO UNDERTAKING WORK



0		Del vices
Date:	UNIE 17, 2010	- /-
Designer:	ALIANA TIMARA	er: 34810
	ALL STOCKTON SERVICES PO BOX 1306	HAMPIONNHUDGISTO
	Daytime Telephone Number: 929-7404 Email Address:	TO CK TON COTTIC, NET
	Fax Number:	
	Name: NIKE Over Permit Number	
Installer:		
	Daytime Telephone Number: 9154-9529 Email Address: M	THEY Promost. Net
	Daytime Telephone Number: 15-29 Email Address: 15-2	Color & Camera
	Fax Number: <u>964-</u> 0487	
Owner:	Name: Jam Wood ward	
	Address: BBOShannon Way, Brentwood,	N. H.
	Daytime Telephone Number: 6777+53 07 Email Address:	
	Fax Number:	
The state of the s	ystem Information:	11111
Town: Brentwood Street: 335han		
Tax Map No: Dot No: Do		
		proval Number: 199147
	n Test: Not Required	T TEST DIT DESILITS
Test Pit Da	ate: Test Pit No.: ATTACI	H TEST PIT RESULTS
T :64	he ISDS qualifies for repair/replacement, answer the following	ng questions:
	the ISDS serve a commercial building?	YES NO NO
		YES D NO D
2. Is the EDA within 75 feet of <u>any</u> surface water or water supply well?		
3. Is the EDA bottom less than 24 inches above the seasonal water table?		YES NO P
4. Any change to dimensions, location, depth, or type of design?		YES NO
	hange in use?	YES NO P
	ncrease in flow?	
IF YOU A	ANSWERED "YES" TO ANY OF THE ABOVE QUESTION ALIFY for repair/replacement of existing systems under Env-W	a 1003.10.
NOT QU	ALIF I for repair/replacement of existing systems under 211.	1
Signatures	S: BY SIGNING, I CERTIFY THAT THE INFORMATION	PROVIDED ABOVE IS TRUE,
COMPLI	ETE, AND NOT MISLEADING TO THE BEST OF MY KN	OWLEDGE AND BELIEF.

Designer: Permit No.: Date: Trave 17, 2010

**CONDITIONS:** Completed Repair/Replacement Questionnaire and sketch MUST be submitted within 10 days of completion of the project.

Contact Information: NHDES, Subsurface Systems Bureau, 29 Hazen Drive, Concord, NH 03302

Telephone: (603) 271-3501 Fax: (603) 271-6683

TEST PIT#1 33 SHANNON WAY BRENTWOOD, NH DATE: JUNE 17, 2010 WINDESS: MIKE CUOMO PIT LOCATION: 12 OFF SDGE OF CHAMBERS AWAY FROM HOUSE 4" ± BELOW EXIS GRADE AT 0-4" TOPSOIL ROOT MAT 4-50" 104R5 6 LOAMY SAND FILL 50-72 IOYR 5/8 FINE SANDY LOAM GRANDLAR FRIABLE (ORIGINAL SUBGRADE) NO EVIDENCE OF SHUTTO 72" (SHWT = 52" + BELOW BED BOTTOM) OK TO REPLACE IN KINT Unnel Hablyh

## N.H. DES SUBSURFACE SYSTEMS BUREAU REPAIR/REPLACEMENT QUESTIONNAIRE - Env-Wq 1003.10(i) and (/) SUBMIT WITHIN 10 DAYS OF COMPLETING WORK



	J. Company of the Com	ivices	
Date Work	Completed: 0000 June 23, 2010		
Designer:			
	Address: DDDD POBER 1306 Hampton NH.		
	Daytime Telephone Number: DDDD 929-7404		
Installer:	Name: DODO Mike olier Permit Number: DODO 789		
mstanci.	Address: 0000 41 Birch Rd No Hampton N.H.		
	Daytime Telephone Number: 0000 964-9529		
Dwner: Name: Doll Ton Woodward Daytime Telephone Number: Doll			
	Address: DODDO 33 ShanronWay  Brentwood Not.		
* . *	Brentwood Not.		
Lot Location			
Tax Map No	0: 0000 2 61 Lot No: 0000 2 2		
Water Supp	ply (check one): Undividual		
	ants (check one): 1 2 3 4 5 6 More than 6 (#:)		
	oms (check one): $\Box 1 \ \Box 2 \ \Box 3 \ \Box 4 \ \Box 5 \ \Box 6 \ \Box More than 6 (#:)$		
	Items (check all that apply): Garbage Grinder Washing Machine Chlorinator		
	Dishwasher		
	outer. databa		
Sewage Disp	sposal System (ISDS)		
	sposal (check all that apply): -ground Pressure Distribution		
	-ground Raised Pressure Distribution renches Drywell		
permag	pe-and-stone		
	ther (specify) [ ] In Ciltraturs		
Age of	of System: DDDD years 17		
Septic Tank			
	New (if applicable): Size: DDDD gallons Type: DDDDD		
Average time	ne between pumping of Septic Tank:		
Opinion as t	to why repair/replacement was needed:		
Age	Excessive load (volume) Inappropriate load (chemicals,		
Other:	SALt-Softener		
ATTACH S	SKETCH REQUIRED BY Env-WQ 1003.10(i) - (k), SIGNED BY PERMITTED DESIGNER		
	BY SIGNING, I CERTIFY THAT THE INFORMATION PROVIDED ABOVE IS TRUE, COMPLETE,		
AND NOT N	MISLEADING TO THE BEST OF MY KNOWLEDGE AND BELIEF.		
_	Mike offer	761	
Installer:	mc del Permit No.: 0000 789 Date: 0000 June 22	1 201	

Designer: Anne Bialobrzes Kipermit No.: 0000 348 Date: 0000 June 22, 2010

Contact Information: NHDES, Subsurface Systems Bureau, 29 Hazen Drive, Concord, NH 03302

Telephone: (603) 271-3501 Fax: (603) 271-6683